

Vehicle History Report

VEHICLE DETAILS

Chassis number ¹ :	GWS204-0007868	Title information ² :		Deregistered to Export	0
Manufacture date:	2008-09		u _		
Make:	ΤΟΥΟΤΑ	Accident / Repair:	I ⇒	No problem	\checkmark
Model:	CROWN	Odometer rollback:		No problem	\bigcirc
Body:	DAA-GWS204	Manufacturer	~		
Grade:	HYBRID	recall:	9	Problem found	×
Engine:	2GR-1KM	Safety grade ³ :	8	*****	\bigcirc
Drive:	2WD	Contamination			
Transmission:	AT	risk:	Å	No problem	v

This vehicle does not qualify for Buyback Guarantee

Average Market Price



Unfortunately, this vehicle does not qualify for our Buyback Guarantee program.



About Buyback Guarantee

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2022-03-19 21:15:24. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2015-09-28	MLIT	31400
2017-09-22	MLIT	59400
2019-10-15	TAA Hiroshima	132598
2019-10-25	USS Osaka	133000

USE HISTORY

Use in the contaminated regions ⁴	Radioactive contamination test fail ⁵	Commercial use
Not reported	Not reported	Not reported

DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2008-09			ΤΟΥΟΤΑ	Manufactured
2008-09			MLIT	First registration
2015-09-28		31400	MLIT	Inspection
2017-09-22	Hiroshima	59400	MLIT	Inspection

2019-10-15	Hiroshima		MLIT	Last registration
2019-10-15	Hiroshima	132598	TAA Hiroshima	Auctioned
2019-10-25	Osaka	133000	USS Osaka	Auctioned

MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
2014-10-15	MLIT	Fuel hose/pipe	In the fuel pipe of the prime mover (delivery pipe), for smoothness of the fuel pressure sensor fastening surface is inappropriate, there are things that entered into force even tighten the fuel pressure sensor to the specified torque is insufficient. Therefore, the fuel pressure sensor fastening portion is loose, there is a possibility that the fuel leaks.
2016-04-13	MLIT	Other (Other)	In the audio amplifier, since there is no circuit for protecting the speaker driving element near the cooling opening, if the element is short-circuited due to a foreign matter or the like, an overcurrent flows and the element is damaged. Therefore, the board burns out, and in the worst case, the flammable gas at the time of burning the board may ignite, resulting in fire.
2020-06-24	MLIT	Other (electrical device)	In an audio amplifier, if the circuit configuration is improper, and a short circuit occurs in a circuit where the influence of foreign matter is not taken into consideration, the existing protection circuit may not function and the board may be burned. Therefore, flammable gas is generated, which may lead to a fire in the worst case.


VEHICLE ASSESSMENT⁶

Overall Collision Safety Ratings

	Driver's	seat		Front passeng	er's seat
Points	Evaluation	Goal average	Points	Evaluation	Goal average
33.81	*****	94%	22.5	*****	94%

* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

Braking performance tests ⁷



51.4 m

VEHICLE SPECIFICATION

1st gear ratio		2nd gear ratio	
3rd gear ratio		4th gear ratio	
5th gear ratio		6th gear ratio	
Additional notes		Airbag position, capacity	
Body rear overhang		Body type	SEDAN
Chassis number embossing position		Classification code	4
Cylinders	6	Displacement	3450
Electric engine type		Electric engine maximum output	
Electric engine maximum torque		Electric engine power	
Engine maximum power	296PS(218KW)/6400RPM	Engine maximum torque	375KG*M(3680NM)/4800RPM
Engine model	2GR-1KM	Frame type	
Front shaft weight	940	Front shock absorber type	DOUBLE WISHBONE COIL SPRING
Front stabilizer type		Front tires size	225/45R18 91W
Front tread	1535	Fuel consumption	
Fuel tank equipment	65	Grade	HYBRID
Height	147	Length	487
Main brakes type		Make	ΤΟΥΟΤΑ
Maximum speed		Minimum ground clearance	
Minimum turning radius	5200	Model	CROWN

Model code	DAA-GWS204	Mufflers number	
Rear shaft weight	920	Rear shock absorber type	MULTI LINK TYPE COIL SPRING
Rear stabilizer type		Rear tires size	225/45R18 91W
Rear tread	1535	Reverse ratio	
Riding capacity	5	Side brakes type	
Specification code	16052	Stopping distance	
Transmission type	AT	Weight	1860
Wheel alignment	2WD	Wheelbase	2850
Width	179		

AUCTION DATA

Date: 2019-10-15, Auction: TAA Hiroshima, Lot #: 324


Date:	2019-10-15	Lot #:	324
Auction name:	TAA Hiroshima	Region:	Hiroshima
Make:	ΤΟΥΟΤΑ	Model:	CROWN HYBRID
Reg. year:	2008	Mileage (km):	132598
Displacement (cc):	3500	Transmission:	AT
Color:	PEARL	Model code:	GWS204
Result:	sold	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	ОК

Date: 2019-10-25, Auction: USS Osaka, Lot #: 56

Date:	2019-10-25	Lot #:	56
Auction name:	USS Osaka	Region:	Osaka
Make:	ΤΟΥΟΤΑ	Model:	CROWN HYBRID
Reg. year:	2008	Mileage (km):	133000
Displacement (cc):	3500	Transmission:	AT
Color:	PEARL	Model code:	GWS204

Result:	available	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	ОК

PHOTOS AND AUCTION SHEETS



A:キス~U:ヘコミ B:セス~を伴うヘコミ P:要塗装 W:補修跡 S:鎬 C:腐食 G:フロントがラス点セス~XX:交換済み X:要交換 内・外装評価 5段階ランク順(A・B・C・D・E) 1



ファーストコーナー 評価点 / 摩 歴 (自家用以外は記入) 装気量 및 式 8500 DAA-GWAJOK BRATH JU-F 2000 56 松茸葉酸年月 草 名 2WD 20/9 # 177>HV So 内装 観時 4WD C RAWESO 月 271 W ※必ず油性ボールベンをご使用下さい。水性ボールベンは使用で 車検 £ A 32.600 HA 走行 セールスポイント 冷閒 の第本第三ート(エアミート 外元音 白朝 日 パー・ハーー 昭 ガンリア・服道・(カラーね 新建築委学編 (保証最付) 062 り鉄道に○をつけ @ fy73, 2-771 有 内着台 ロレダークル・ズコントロール ¥ 名職室更離職 ■入業分 ハンドを のからえやト スマーキー B 月 ディーラー・並行 を ・ 右 1719h 18/80 4826 2 # M 章台靴 下さい GW,200x-0007860 〇注意事項(##・不具合業所および状態等) シリアルね QX-A-HODTE TAKE Ky7 AX7 A2 0/17-2-10712/ TV Q EN HAZETU Q 7177227-○検査員報告(USS使用欄) FF-A ...ルーム内ウス:うれ、スレ 10 22 3-FA9% せん 62 11411th たイール ミラ- tx (商台內寸)的 × × (cm) At on At cm 1 (事業版上の寸法) 長さ 247 AND A LA DESIGN DESIGN







¹ Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

² Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped Deregistered to Export – not qualified for driving in Japan , the vehicle is determined to be exported

³ Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

⁴ **Use in the contaminated regions** – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

⁵ Radioactive contamination test – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

⁶ Japan New Car Assessment Program – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test , rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

⁷ **Braking Performance Tests** – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2022 Car VX Limited. All rights reserved.