



Vehicle History Report

VEHICLE DETAILS

Chassis number ¹: HA9-1007865

Manufacture date: 2010-02-18

Make: HONDA

Model: ACTY TRUCK

Body: EBD-HA9

Grade: ATTACK

Engine: E07Z

Drive: 4WD

Transmission: F5

Title information ²:  **Deregistered to Export** 

Accident / Repair:  **No problem** 

Odometer rollback:  **No problem** 

Manufacturer recall:  **No problem** 

Safety grade ³:  **No data** 

Contamination risk:  **No problem** 

This CAR VX Vehicle History Report is based only on Information supplied to CAR VX, LTD and available as of 2026-01-27 18:14:00. Other information about this vehicle, including problems, may not have been reported to CAR VX, LTD . Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

ACCIDENT / REPAIR HISTORY

Problem type	Reported	Date reported	Data source	Details	Airbag
Collision	Not reported				
Malfunction	Not reported				
Theft	Not reported				
Fire damage	Not reported				
Water damage	Not reported				
Hail damage	Not reported				

ODOMETER READINGS HISTORY

Date reported	Data source	Odometer reading (Km)
2022-02-10	MLIT	32400
2024-01-31	MLIT	34600
2025-09-30	CAA Gifu	38485


USE HISTORY

Use in the contaminated regions ⁴	Radioactive contamination test fail ⁵	Commercial use
Not reported	Not reported	Not reported

DETAILED HISTORY

Event date	Location	Odometer reading (Km)	Data source	Details
2010-02-18			HONDA	Manufactured
2010-02			MLIT	First registration
2022-02-10		32400	MLIT	Inspection
2024-01-31	Aichi	34600	MLIT	Inspection
2025-09-30	Gifu	38485	CAA Gifu	Auctioned

MANUFACTURER RECALL HISTORY

Date reported	Data source	Affected part	Details
 Not reported			

VEHICLE ASSESSMENT ⁶

Overall Collision Safety Ratings

Driver's seat			Front passenger's seat		
Points	Evaluation	Goal average	Points	Evaluation	Goal average
0		0%	0		0%

* In order to accurately differentiate between the evaluations of different vehicles, a standard is set based on current technology. Up to 6 points out of 12 is given level 1 and the rest of the range is divided up into equal parts, which are respectively assigned to level 2 (more than 6 points but 7.5 or less), level 3 (more than 7.5 points but 9 or less), level 4 (more than 9 points but 10.5 or less) or level 5 (more than 10.5 points).

Braking performance tests ⁷

Dry road



Wet road



VEHICLE SPECIFICATION

1st gear ratio

2nd gear ratio

3rd gear ratio

4th gear ratio

5th gear ratio

6th gear ratio

Additional notes

2, 16W, 33 FLAT
PERSONCMAirbag position,
capacity

Body rear overhang

Body type

LIGHT TRUCK

Chassis number embossing position	CABIN BACK PANEL FRONT SURFACE	Classification code	0001
Cylinders		Displacement	650
Electric engine type		Electric engine maximum output	
Electric engine maximum torque		Electric engine power	
Engine maximum power	45ps(33kW)/5500rpm	Engine maximum torque	6.0kg· m(59N· m)/5000rpm
Engine model	E07Z	Frame type	
Front shaft weight	490	Front shock absorber type	
Front stabilizer type		Front tires size	145R12-6PR LT
Front tread	1295	Fuel consumption	
Fuel tank equipment	37	Grade	ATTACK
Height	174	Length	339
Main brakes type		Make	HONDA
Maximum speed		Minimum ground clearance	
Minimum turning radius	3.7	Model	ACTY TRUCK
Model code	EBD-HA9	Mufflers number	
Rear shaft weight	330	Rear shock absorber type	
Rear stabilizer type		Rear tires size	145R12-6PR LT
Rear tread	1310	Reverse ratio	
Riding capacity	2	Side brakes type	
Specification code	16400	Stopping distance	
Transmission type	F5	Weight	820
Wheel alignment	4WD	Wheelbase	1900
Width	147		

Date: 2025-09-30, Auction: CAA Gifu, Lot #: 30174

Date:	2025-09-30	Lot #:	30174
Auction name:	CAA Gifu	Region:	Gifu
Make:	HONDA	Model:	ACTY TRUCK
Reg. year:	2010	Mileage (km):	38485
Displacement (cc):	660	Transmission:	F5
Color:	BLUE	Model code:	HA9
Result:	sold	Auction grade:	4
Problem type:	No problem	Problem scale:	None
Contaminated:	No	Airbag:	OK


PHOTOS AND AUCTION SHEETS

出品番号	初度登録	車名	ドア形状	グレード	評価点
30174 初出品	H22年	アクティトラック		アタック 4WD	4
	2月	自家用	排気量 660 cc	燃料 ガソリン	型式 EBD-HA9
					外装 内装
					C B

走行	車検	登録番号	譲渡書類期限	セールスポイント	
38,485 km	年 月		月 日	★ユーザー買取車!! ★ETC ★荷台ランプ	
シフト	エアコン	外装色	乗車定員	最大積載量	
F5	ナシ	アオ	2人	kg	
		カラーNo.	輸入車	リサイクル預託金	
		PB70	系	5,630円	
後日発送部品				純正装備	
				I7B PS	

注意事項欄			車台番号		
			HA9-1007865		
			諸元		
長さ		幅	高さ		

検査員記入欄
下廻りS 外装色あせ スタッドレスタイヤ
事務局よりご案内



A:キズ U:欠陥 B:キズを伴う欠陥 P:要塗装 W:補修箇 S:錆 C:腐食、穴 G:ボディ材の2点キズ XX:交換済み X:要交換 欠:欠品 内・外装評価 5段階5段階順(A・B・C・D・E) 1

















¹ Chassis number – a unique identification number of the vehicle in Japan (same as VIN in the USA or Europe)

² Title information:

Registered – qualified for driving in Japan

Deregistered Temporarily – not qualified for driving in Japan, usually a temporary title during the ownership change

Deregistered Completely – not qualified for driving in Japan, the vehicle is determined to be scrapped

Deregistered to Export – not qualified for driving in Japan, the vehicle is determined to be exported

³ Determining the overall collision safety performance evaluation – For the driver's seat, the results of the full-wrap frontal collision test, offset frontal collision test, and side collision test are added together and evaluated to 6 different levels. For the Frontal passenger's seat, the results of the full-wrap frontal collision test and the side collision test (results for the driver's or the front passenger's seat are used) are added together and evaluated to 6 different levels.

Regular vehicle inspection – All vehicles in Japan must undergo regular vehicle inspections (shaken). New cars need to be tested after three years, and then vehicles must be tested every two years thereafter. A vehicle inspection (shaken) is compulsory for all vehicles with an engine size over 250cc. It ensures that all vehicles on the road are properly maintained and safe to drive. The test also checks that vehicles have not been illegally modified; if they are found to have been modified, they are not allowed on the road.

⁴ Use in the contaminated regions – The Fukushima Daiichi nuclear disaster was a catastrophic failure at the Fukushima I Nuclear Power Plant on 11 March 2011, resulting in a meltdown of three of the plant's six nuclear reactors. As a result, some areas in the following prefectures were contaminated: Fukushima, Miyagi, Ibaraki, Tochigi.

⁵ Radioactive contamination test – radioactive contamination inspection that was started in July 2011 as a preventive measure for exporting contaminated vehicles from Japan. The inspection is being conducted since in all sea ports of Japan under the supervision of The Japan Harbor Transportation Association (JHTA).

MLIT – Ministry of Land, Infrastructure, Transport and Tourism.

⁶ Japan New Car Assessment Program – the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) and the National Agency for Automotive Safety & Victims' Aid (NASVA) have taken measures for safety, one of which is to assess commercially available vehicles through a variety of safety performance tests and release the resulting information compiled into the "New Car Assessment Program". The objective of Japan New Car Assessment Program is to increase the use of safe automobiles by providing an environment in which users can easily select such vehicles. This also promotes the development of safer vehicles by automobile manufacturers. Neck injury protection for rear-end collision performance test, rear seat passenger's protection for frontal collision performance test, rear passenger's seat belt usability evaluation test and seat belt reminder for passengers evaluation test are started in FY2009.

⁷ Braking Performance Tests – Braking performance is determined by the shortness of the distance in which a vehicle can stop and the stability of the vehicle at the time of braking. This test is performed under wet and dry road conditions for a vehicle which has both a driver and a front passenger. The distance it takes for the vehicle to stop and the stability of the vehicle at the time of braking is evaluated for when the vehicle is stopped abruptly while traveling at a speed of 100km/h. The stopping distance and vehicle speed have been measured by using GPS since FY2009.

CAR VX, LTD DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CAR VX, LTD OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CAR VX, LTD FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2014-2026 Car VX Limited. All rights reserved.