

vehicle interior, potentially causing serious or fatal injuries to vehicle occupants.

If your vehicle is affected by the recall, please contact your Volkswagen retailer as soon as possible to have the affected components replaced quickly and free of charge. The replacement usually takes only about one hour.

[Find your Volkswagen retailer](#)

Your safety is important to us. That's why we ask you to have your vehicle checked and repaired without delay.

Here you can check whether your vehicle is affected

Dear Volkswagen Customer,

Your vehicle with the Vehicle Identification Number (VIN) WVWZZZAAZDD061039 had a Takata airbag at the time of delivery and has already been repaired as part of a Takata airbag recall.

Therefore, no further action is required on your part.

We appreciate your trust in the Volkswagen brand and look forward to continuing to count on your loyalty.

Sincerely,
Volkswagen AG

Your vehicle has been repaired.

[New request](#)

[Download](#)

What is a VIN and where do I find it?

The VIN is a unique and internationally standardised vehicle identification number. The 17-digit number can be found in the Part I of the registration certificate, formerly known as the registration document, and in the lower area of your windscreen.