

4-Wheel Recall, Improvement Measures, and Service Campaigns Target Vehicle Search

Chassis number enteredRK5-1409349

All vehicles with the chassis number entered by the customer have been recalled.
You can use it with confidence.

[Search results: Implemented] The following shows the past implementation history.

division	Date of notification (start date)	Notification Number	Contents (Click below to check the details of the measures)
Remedial Measures	2018-11-15 Notification	558	Tailgate open stay defect Measures

Inquiries

クルマ(車両)

Hondaお客様相談センター

0120-112010

受付時間:9時~12時/13時~17時

