4-wheel Recall, improvement measures, and service campaigns Target vehicle search

The entered chassis number RC1-1107466

The vehicle with the chassis number you entered has had all recalls and other issues carried out, so you can use it with peace of mind.

[Search results: Completed] The following shows the past implementation history.

classification	Notification date (start date)	Notification number	Details (Click below to view details of measures)
recall	2017-10-26 Notification	Country 4130	Door mirror switch replacement procedure

■ **Inquiries**

クルマ(車両)

■Hondaお客様相談センター

0120-112010

受付時間:9時～12時/13時～17時

閉じる

(C) Honda Motor Co., Ltd. and its subsidiaries and affiliates. All Rights Reserved.